

**Id** 1741419  
**License plate** 9961MLT  
**Frame** TMBGR6NWX3186790  
**Brand** SKODA  
**Model** KAMIQ  
**Submodel** SK KAMIQ 1.0 TSI 110CV  
**Color** WHITE  
**Client** EUROPCAR MOBILITY GROUP SPAIN  
**Location** MADRID  
**Rate** 64255\_EMG B2B TURISMOS\_9037\_ES\_2022  
**Order**

**Km** 72173  
**Valuation Date** 17/03/2026

| Element               | Action  | Level     | RT   |
|-----------------------|---------|-----------|------|
| Right mirror housing  | Paint   | Minor     | 0.00 |
| Front bumper (remove) | Paint   | Minor     | 0.60 |
| Front bumper moulding | Paint   | Minor     | 0.00 |
| Bonnet                | Dent    | Minor     | 0.30 |
| Fender front left     | Dent    | Minor     | 0.30 |
| Left mirror housing   | Paint   | Minor     | 0.00 |
| Door front left       | Dent    | Minor     | 0.20 |
| Door rear left        | Dent    | Minor     | 0.30 |
| Rear bumper (remove)  | Paint   | Minor     | 0.60 |
| Rear bumper moulding  | Paint   | Minor     | 0.00 |
| Fender rear right     | Dent    | Minor     | 0.30 |
| Door front right      | Forfait | polishing | 0.00 |

total appraisal 0.00 €

Images



Picture - 1



Picture - 2



Picture - 3



Picture - 4



Picture - 5



Picture - 6



Picture - 7



Picture - 8



Picture - 9



Picture - 10



Picture - 11



Picture - 12



Picture - 13



Picture - 14



Picture - 15



Picture - 16



Picture - 17



Picture - 18



Picture - 19



Picture - 20



Picture - 21



Picture - 22



Picture - 23



Picture - 24



Picture - 25



Picture - 26



Picture - 27



Picture - 28



Picture - 29



Picture - 30



Picture - 31



Picture - 32



Picture - 33



Picture - 34



Picture - 35



Picture - 36



Picture - 37



Picture - 38



Picture - 39



Picture - 40



Picture - 41



Picture - 42



Picture - 43



Picture - 44



Picture - 45